



Completed Box



Hinge or cleat roof for access and cleaning. Wire close.

Put 3" of sawdust in the bottom of the box.

Lumber: 1" x 10" x 8'